



The Best Place on Earth

Structural Integrity Assessment Report

Commercial Vehicle Safety and Enforcement Division (CVSE)

Designated Inspection Facility Information

ASSESSMENT RESULTS

PASS

FAIL

Facility Number 31681

Facility Name Greenline Ltd

Authorized Inspector Number W11228

Inspector Name Sam Poore

Inspector Signature [Signature]

Date 20th April 2012

Vehicle Information

OWNER [Redacted]

ADDRESS [Redacted]

CITY Vancouver

PROV. BC

POSTAL CODE [Redacted]

REGISTRATION NUMBER [Redacted]

PLATE NUMBER [Redacted]

YEAR 2009

MAKE Subaru

MODEL Legacy

BODY STYLE Sedan

VIN # 4S3BL846194021903



Section B

Light Vehicle Section - Safety and Repair Inspection Standards
Inspection Vehicle Inspection Manual BC Regulation 103/2002

PASS FAIL

1. HOOD				WHEEL ALIGNMENT (ALL FOUR WHEELS OR AT LEAST FRONT IF AVAILABLE) ALIGNMENT PERFORMED AT <u>AN MECHANICS</u> PLEASE INDICATE NUMBERS AND MEASUREMENTS ON DIAGRAM BELOW
2. BODY/CYBASS				
3. TR. FRAME AND/OR STRUCTURAL BODY COMPONENTS				
4. BUMPER FRONT AND REAR				
5. DOORS				
4. TR. UNIBODY STRUCTURAL INTEGRITY				
23. WELDING				
REPAIRS DONE COMPARABLE TO ORIGINAL CORROSION PROTECTION				
UNREPAIRABLE STRUCTURAL COMPONENTS REPLACED				
ASSEMBLY JOINTS OF BODY IN PROPER LOCATIONS				
SEALANT SOUND AND OPTIMAL, (JUST PROTECTIVE COMPOUND NOT APPLIED TO REPAIR AREA PRIOR TO INSPECTION (PASSED VEHICLES ONLY))				
COMPONENTS OF CHASSIS BY THE LIMITED BODY ASSEMBLY SO AS NOT TO AFFECT THE MECHANICAL AND METALLURGICAL PROPERTIES OF THE MATERIALS				
COMMENTS (ATTACH PAGES IF REQUIRED)				ALIGNMENT <input checked="" type="checkbox"/> PASS <input type="checkbox"/> FAIL

Indicate on the appropriate diagram, areas of the vehicle that have been repaired or modified



I certify that this vehicle was inspected according to the structural integrity criteria as detailed in the body integrity section of the Safety and Repair Inspection Standards Regulations, B.C. Reg 103/2002 as amended, and that the vehicle alignment is within the vehicle manufacturer's specifications for this vehicle.

Repair Facility Name G.N. AUTOBODY LTD

3001 - 2ND AVE
BURNABY BC V5C 3W0
(604) 293-7777
FAX (604) 293-7701

Autobody Technician's Name Urbano Atkins

Signature [Signature]

TC Number 01306-AB-07

The original of this form must be forwarded to the designated inspection facility indicated above, and must be retained by that facility. A photocopy must accompany the customer's copy of the MV3199 report.

The personal information on this form is collected under the authority of the Motor Vehicle Act, Section 217. The information will be used to process the vehicle inspection.

Q001075

MV3201 (08/2009)